SERVICE BULLETIN

ProDuct : AUDIO

Bulletin No. : 2000-AUD-E0010

MODEL : ALL MODEL

Bulletin Date : NOV 07.2000

Buyer : ALL BUYER

ECN & data : NOV 06.2000

SUBJECT : Inform for Service Manal of CD DECK ASS'Y and Pick-up

Background : Change to correct parts of CD DECK and Pick-up

Cause : Printing error

Solution : - CD Deck Ass'y(Pick-up) is identified by the specification printed on the body of it.
For ordering CD Deck Ass'y(Pick-up),refer to the below table.

Application Date : Running Change

NO	PICK-UP		CD DECK ASS'Y		Remark
	SEC CODE	SPECIFICATION	SEC CODE	SPECIFICATION	
1	AJ30-20001B	SOH-AP(APU)	AJ59-20003F	CMS-P30AM6/NM6	
2	AJ30-20001A	SOH-A1(A1U)	AJ59-20001A	CMS-A30AG6	
3	AJ75-00601F	SOH-AA(AAU)	AH59-20005N	CMS-B31TG6	
4	AH30-00003A	SOH-AD(ADU)	AH91-60150A	CMS-D51SG6	
5	AH30-00007A	SOH-AD3(AD3U)	AH91-60150B	CMS-D73SG6	

Attachment Schematic Diagram ( ) Component Lay-out ( ) PCB Diagram ( )
Mechanical Diagram( ) None ( ) Others ( )

Published by :	Checked by :	Approved by :